

Category	Details
Project Name	x
Project ID	х
Project Location	х
Company Name	ICoM GmbH
Inspector Name	Max Mastermann
Date of Inspection	02/04/2025
Damage & Object Type(s)	Graffiti, Weathering, PEquipment (Protective Equipment)
Impact	The graffiti and weathering have caused damage to the concrete wall, including the railway track, which is a piece of equipment.
Size	The damage is estimated to be around 10 cm² for the graffiti and 20 cm² for the weathering.
Direction	Horizontal (graffiti) and vertical (weathering).
Possible Reasons	The graffiti and weathering have exposed the underlying concrete, leading to damage to the railway track.