CRAWLER CRANE CHECKLIST

Certificate No.	2026-22108-0058-008	**Ref. Standard**	SASO ISO 20474-2 ASME B30.5:2021
Serial No.	656		

Description **General Requirements**	**PASS**	**FAIL**	**N/A**	**REMARKS**
Equipment documentation is available	☒	☐	☐	
Preventive Maintenance is established and dated records are maintained	☒	☐	☐	
Previous inspection reports are checked	☒	☐	☐	
Durable load chart is provided in an accessible location	☒	☐	☐	
Work areas chart is available	☒	☐	☐	
Operator is certified (for the inspected crane type/model) and licensed	☒	☐	☐	
Fire extinguisher is in place with minimum rating 10 BC	☒	☐	☐	
Markings and direction of all control levers are clearly displayed	☒	☐	☐	
Crane Safe Load Indicator / SLI , RCL is working in aproper ways as per load chart	☒	☐	☐	
MVPI Document is available and valid	☒	☐	☐	
Reverse travel alarm is operational.	☒	☐	☐	
Turning signals and indicators are working correctly	☒	☐	☐	
Road lighting, including spotlights, are in good condition and operable	☒	☐	☐	
Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	☒	☐	☐	
Horn and wind speed anemometer are working	☒	☐	☐	
Crane level indicator is fitted and working	☒	☐	☐	
Engine gauges and associated indicators are working	☒	☐	☐	
The warning sign stating power line required clearances is visible to the operator	☒	☐	☐	
All cab glazing are safety glazing material	☒	☐	☐	
Verify cab doors functionality and condition	☒	☐	☐	
Seat belt is fitted and in good condition	☒	☐	☐	
Walking platforms and areas of structure are skid-resistance	☒	☐	☐	
Safe Load Indicator (SLI) / SLL Is workinf in proper way .	☒	☐	☐	

Kingdom of Saudi Arabia – Main Office – Eastern Province
Al Khobar, 6205 Prince Muteb St, Al-Sharq Tower, 5th Floor
Phone: 0138185501 - Mob: +966566485177
E-Mails: info@tuv-east.com - Website: www.tuv-east.com

LEEA Full Member

Load block sheaves turn freely and are undamaged	☒	☐	☐	
Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	☒	☐	☐	
Hook assemblies are equipped with safety latches	☒	☐	☐	
Hook assembly labeling and manufacturer data is clearly marked	☒	☐	☐	
Hook's weight is clearly marked/printed on the hook	☒	☐	☐	
Safe working load of hook is clearly marked on the item	☒	☐	☐	
Hook does not show defects such as nicks, cracks and gouges	☒	☐	☐	
Hook is not bent or twisted • Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations	☒	☐	☐	
Hook is not distorted in the throat opening • Max. allowable throat opening is 5% compared to new hook, or as per manufacturer recommendations	☒	☐	☐	
Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	☒	☐	☐	
Hook is not cracked, gouged or shows nicks	☒	☐	☐	
Hook can lock (if it is a self-locking hook)	☒	☐	☐	
Inoperative latch (if provided) — any damaged latch or malfunctioning latch that does not close the hook's throat	☒	☐	☐	
Rope guards and locked in position with pins (hook block)	☒	☐	☐	
Dead end rope anchor is fitted with a lock pin (hook block)	☒	☐	☐	
Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	☒	☐	☐	
Track pads are undamaged and drive chain are tensioned	☒	☐	☐	
Drive sockets and drive chain tumblers are serviceable	☒	☐	☐	
Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	☒	☐	☐	
Track idlers are serviceable	☒	☐	☐	
Back boom stops are functioning	☒	☐	☐	
Back A-Frame is in good condition	☒	☐	☐	
Boom cut-out (at maximum angle) is operable	☒	☐	☐	
Power low lowering is operational	☒	☐	☐	
Boom hoist safety auxiliary ratchet / pawl lock is engaging	☒	☐	☐	
Boom chords and lacings are undamaged (bent)	☒	☐	☐	

Kingdom of Saudi Arabia – Main Office – Eastern Province
Al Khobar, 6205 Prince Muteb St, Al-Sharq Tower, 5th Floor
Phone: 0138185501 - Mob: +966566485177
E-Mails: info@tuv-east.com - Website: www.tuv-east.com

Sheave grooves are free from surface defects that could cause rope damage.	☒	☐	☐	
Operation of steering brakes is satisfactory	☒	☐	☐	
Main machinery guarding is in place	☒	☐	☐	
Main clutch is fully operational	☒	☐	☐	
Main boom and hoist drum brakes are fully functional	☒	☐	☐	
LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3-ton cranes or more)	☐	☐	☒	

Inspector Name	Inspector Signature	Date of Inspection
Omar Khalid		19-Oct-2026

Kingdom of Saudi Arabia – Main Office – Eastern Province
Al Khobar, 6205 Prince Muteb St, Al-Sharq Tower, 5th Floor
Phone: 0138185501 - Mob: +966566485177
E-Mails: info@tuv-east.com - Website: www.tuv-east.com

LEEA Full Member