Change List

01_Vesion 1.0 Created at 2017/4/4

XD.N09001AA

02_Vesion 1.1 Created at 2017/5/5

XD.N09001BA

01_Fixed phase current amplifying circuit bias bug

02_Delete reset button

03_Re-layout MA700

for correct magnetic field direction measurement

04_Add Test Point for externally mount MA700

Motor Driver Board_Pitch Or Roll

01_INDEX

02_Block Diagram

03_Power

04_STM32

05_MOS Driver

06_3H-Bridges MOS+Shunt Resistor

07_Phase Current and Voltage Sensor

08_MA700

| O1_INDEX | | O1_INDEX | | O1_INDEX | | O1_INDEX | O1_



















