Change Order Report For Project TRX-101R17.PrjPcb And TRX-101R17.PrjPcb

ion	Object		Change Document	Status
nove Pins	From Nets			
Remove	C54-1 from GND_SIGNAL	In	TestCase1.PcbDoc	
Remove	C55-1 from GND_SIGNAL	ln	TestCase1.PcbDoc	
Remove		ln	TestCase1.PcbDoc	
Remove	R28-2 from +5V	ln	TestCase1.PcbDoc	
Remove	R32-1 from GND_SIGNAL	In	TestCase1.PcbDoc	
Remove		In	TestCase1.PcbDoc	
Remove	R45-2 from +5V	In	TestCase1.PcbDoc	
Remove	U10-1 from GND_SIGNAL	In	TestCase1.PcbDoc	
Remove	U10-4 from +5V	In	TestCase1.PcbDoc	
Remove	U10-8 from +5V	ln	TestCase1.PcbDoc	
Remove	U11-2 from GND_SIGNAL	ln	TestCase1.PcbDoc	
Remove	U11-5 from +5V	In	TestCase1.PcbDoc	
emove Nets				
Remove	NetR5_1	From	TestCase1.PcbDoc	
Remove	NetU3_4	From	TestCase1.PcbDoc	
Remove	NetU10_6	From	TestCase1.PcbDoc	
Remove	NetU11_4	From	TestCase1.PcbDoc	
emove Com				
Remove			TestCase1.PcbDoc	
Remove	C55		TestCase1.PcbDoc	
Remove	R5		TestCase1.PcbDoc	
Remove	R28		TestCase1.PcbDoc	
Remove			TestCase1.PcbDoc	
Remove	R44		TestCase1.PcbDoc	
Remove	R45		TestCase1.PcbDoc	
Remove	U10		TestCase1.PcbDoc	
Remove	U11	From	TestCase1.PcbDoc	
dd Nets				
Add	916_RX_DATA	To	TestCase1.PcbDoc	
	ent Classes			
Add	PG03_Schematic Sheet1	To	TestCase1.PcbDoc	
dd Rooms				
Add	Room PG03_Schematic Sheet1 (Scope=I	То	TestCase1.PcbDoc	
	nComponentClass('PG03_Schematic			
	Sheet1')) TopLayer			