

Datasheet

# Bluetooth AHRS IMU sensor | WT9011DCL-BT5.0

The Robust Acceleration, Angular velocity, Angle & Magnetic filed Detector

The WT9011DCL-BTL5.0 is a Bluetooth 5.0 multi-sensor device, detecting acceleration, angular velocity, angle as well as magnetic filed. The robust housing and the small outline makes it perfectly suitable for industrial applications such as condition monitoring and predictive maintenance. Configuring the device enables the customer to address a broad variety of application by interpreting the sensor data by smart algorithms and Kalman filtering.

#### **BUILT-IN SENSORS**







Accelerometer

Gyroscope

Magnetometer



### **Tutorial Link**

#### **Google Drive**

Link to instructions DEMO: WITMOTION Youtube Channel WT9011DCL-BT5.0 Playlist

If you have technical problems or cannot find the information that you need in the provided documents, please contact our support team. Our engineering team is committed to providing the required support necessary to ensure that you are successful with the operation of our AHRS sensors.

### **Contact**

**Technical Support Contact Info** 

# **Application**

- Unmanned/Assisted Driving
- Large-scale farming automated farming
- Safety monitoring for working at heights
- Unmanned aerial vehicle
- Industrial attitude monitoring
- Human motion tracking/capture
- Robot, Automated Guided Transporter
- Pedestrian Navigation
- Truck-mounted Satellite Antenna Equipment



# **Contents**

Tutorial Link 2 -
Contact 2 -
Application 2 -
Contents 3 -
1 Overview 4 -
2 Features 5 -
3 Specification 6 -
3.1 Parameter 6 -
3.2 Size 8 -
3.3 Axial Direction 9 -
4 Port Definition 10 -
5 Casing Specification 11 -
6 Communication Protocol 12 -
6.1 Data Format 12 -
6.1.1 Data Packet(Default) 12 -
6.1.2 Single Return Register Data Packet 15 -
6.2 Commands 18 -
6.2.1 Read Register Value 18 -
6.2.2 Calibration 18 -
6.2.3 Save Settings 19 -
6.2.4 Return Rate 19 -
6.3 Register Address 20 -



## 1 Overview

WT9011DCL-BT5.0's scientific name is AHRS IMU sensor. A sensor measures 3-axis angle, angular velocity, acceleration, magnetic field. Its strength lies in the algorithm which can calculate three-axis angle accurately.

WT9011DCL-BT5.0 is an CE certified accelerometer. It is employed where the highest measurement accuracy is required. WT9011DCL-BT5.0 offers several advantages over competing sensor:

- Heated for best data availability: new WITMOTION patented zero-bias automatic detection calibration algorithm outperforms traditional accelerometer sensor
- High precision Roll Pitch Yaw (X Y Z axis) Acceleration + Angular Velocity + Angle + Magnetic Field output
- Low cost of ownership: remote diagnostics and lifetime technical support by WITMOTION service team
- Developed tutorial: providing manual, datasheet, demo video, free software for Windows computer, APP for Android smartphones, iOS APP for iPhone, communication protocol for project development
- WITMOTION sensors have been praised by thousands of engineers as a recommended attitude measurement solution



### 2 Features

- The sensor integrates high-precision gyroscope, accelerometer and geomagnetic field sensor, and adopts high-performance microprocessor and advanced dynamic calculation and Kalman dynamic filtering algorithm, which can guickly solve the current real-time motion attitude of the sensor.
- The advanced digital filtering technology can effectively reduce the measurement noise and improve the measurement accuracy.
- The sensor is integrated with the attitude solver and the dynamic Kalman filter algorithm, which can accurately output the current attitude of the sensor in the dynamic environment. The attitude measurement accuracy is 0.2 degree, the stability is extremely high, and the performance is even better than some professional inclination meter.
- The Z-axis heading angle is added to the filter fusion of the geomagnetic sensor, which solves the cumulative error caused by the drift of the gyroscope integral in the 6-axis algorithm, and can output the heading angle data stably for a long time. Note: Due to the magnetic field detection, it needs to be calibrated before use, and it needs to be at least 20cm away from magnetic interference areas, electronic equipment, magnets, speakers and other hard magnetic objects.
- Working current: ≈ 14mA, standby current 14uA-30uA.
- Data interface: baud rate 115200.
- The output content can be selected arbitrarily, data output frequency: 0.2Hz~200Hz, ,default 10HZ.
- Bluetooth 5.0 wireless transmission, transmission stability, the longest distance up to 90 meters.
- Bluetooth 5.0: Support Android /IOS operating system (the actual use depends on the final device)
- battery: working time: 8 hours, charging time: 2 hours, capacity: 130mAh



# 3 Specification

# 3.1 Parameter


Parameter	Specification
> Voltage	3.3-5V
> Current	Working current:14mA
	Broadcast current:21mA Stand-by current:14uA-30uA
> Range	Acceleration: ±16g
	Angular Velocity: ±2000°/s
	Magnetic field: ±2Gauss
> Resolution	Angle:X/Z±180°,Y±90°  Acceleration:0.5mg/LSB(2048LSB/g)
, Resolution	Angular Velocity:0.061(°/s)/LSB
	Magnetic field:0.0667mG/LSB
	Angle:0.0055 °/LSB
Accuracy	acceleration: 0.01g, angular speed 0.2°/s
> Output content	Acceleration, Angular Velocity, Angle
	(Magnetic is not output by default)
Distance	up to 90 meters (open area)
Battery	working time: 8 hours, charging time: 2 hours, capacity: 130mAh
> Duration	8 hours
> Size	23.5mm x 32.5mm x 11.4mm
Weight	9g
Data	Angle: X Y Z, 3-axis
	Acceleration: X Y Z, 3-axis
	Angular Velocity: X Y Z, 3-axis  Magnetic Field: X Y Z, 3-axis
	Time, Quaternion
> Output frequency	0.2Hz200Hz, default 10HZ
> Interface	Bluetooth5.0/Type-C
> Bluetooth	Bluetooth Coverage range: ≤90m Built-in Chip: nRF52832



Measurement Range & A	ccuracy	
Sensor	Measurement Range	Accuracy/ Remark
> Accelerometer	X, Y, Z, 3-axis ±16g	Accuracy: 0.01g Resolution: 16bit Stability: 0.005g
> Gyroscope	X, Y, Z, 3-axis ±2000°/s	Resolution: 16bit Stability: 0.05°/s
> Magnetometer	X, Y, Z, 3-axis ±4900μT	0.15μT/LSB typ. (16-bit)
> Angle/ Inclinometer	X, Y, Z, 3-axis X, Z-axis: ±180° Y ±90° (Y-axis 90° is singular point)	Accuracy:X, Y-axis: 0.05° Z-axis: 1°(after magnetic calibration)



# 3.2 Size




Parameter	Specification	Tolerance	Comment
Length	32.5	±0.2	
Width	23.5	±0.2	Unit: millimeter.
Height	11.6	±0.2	omer minimeen
Weight	9	±0.2	Unit: gram



## 3.3 Axial Direction

As shown in the product size drawing. The direction of rotation is defined by the rule of the right hand, that is, the thumb of the right hand points to the axis, and the direction of the four fingers bending is the direction of rotation around the axis.






# **4 Port Definition**



PIN	Function
> Type-C	3.3-5V input supply



# **5 Casing Specification**





# **6 Communication Protocol**

### 6.1 Data Format

Sensor upload Flag=0x61 (Angle, Angular velocity, Acceleration) data default.

Flag=0x71(Magnetic field) need to send the corresponding register instruction.

Upload data format of Bluetooth: uploads up to 20 bytes per data

## 6.1.1 Data Packet(Default)

Packet	Flag bit	axL	axH	 YawL	YawH
heading 1Byte	1Byte				
0x55	Flag	0xNN	0xNN	 0×NN	0xNN

Note: 0xNN is an accurate value received. Data return sequence: Acceleration X Y Z, Angular velocity X Y Z, Angle X Y Z, low byte first, high byte last.

Flag = 0x61 Data content: 18Byte is Acceleration, Angular velocity, Angle.



0x55	Packet header
0x61	Mark bit
axL	X Acceleration low 8 byte
axH	X Acceleration high 8 byte
ayL	Y Acceleration low 8 byte
ауН	Y Acceleration high 8 byte
azL	Z Acceleration low 8 byte
azH	Z Acceleration high 8 byte
wxL	X Angular velocity low 8 byte
wxH	X Angular velocity high 8 byte
wyL	Y Angular velocity low 8 byte
wyH	Y Angular velocity high 8 byte
wzL	Z Angular velocity low 8 byte
wzH	Z Angular velocity high 8 byte
RollL	X Angle low 8 byte
RollH	X Angle high 8 byte
PitchL	Y Angle low 8 byte
PitchH	Y Angle high 8 byte
YawL	Z Angle low 8 byte
YawH	Z Angle high 8 byte

Acceleration calculation method: Unit: g

```
a_x=((axH<<8)|axL)/32768*16g(g is Gravity acceleration, 9.8m/s^2)

a_y=((ayH<<8)|ayL)/32768*16g(g is Gravity acceleration, 9.8m/s^2)

a_z=((azH<<8)|azL)/32768*16g(g is Gravity acceleration, 9.8m/s^2)
```

Angular Calculation method: Unit:°/s

```
w_x = ((wxH << 8)|wxL)/32768*2000(°/s)

w_y = ((wyH << 8)|wyL)/32768*2000(°/s)

w_z = ((wzH << 8)|wzL)/32768*2000(°/s)
```

Angle Calculation method: Unit: °

```
Roll(X axis)Roll=((RollH<<8)|RollL)/32768*180(°)
Pitch(Y axis)Pitch=((PitchH<<8)|PitchL)/32768*180(°)
Yaw angle(Z axis)Yaw=((YawH<<8)|YawL)/32768*180(°)
```



#### Note:

- 1. The coordinate system used in the settlement of attitude Angle is the northeast sky coordinate system, and the sensor is placed in the positive direction. As shown in "4 pin Description", the left axis is the X axis, the forward axis is the Y axis, and the upward axis is the Z axis. When Euler Angle represents the attitude, the rotation order of the coordinate system is defined as Z-Y-x, that is, first rotate around the Z axis, then rotate around the Y axis, then rotate around the X axis.
- 2. Although the range of the roll Angle is  $\pm 180$  degrees, in fact, because the coordinate rotation order is Z-Y-X, the range of the pitch Angle (Y-axis) is only  $\pm 90$  degrees when the attitude is expressed. When it exceeds 90 degrees, it will be changed to less than 90 degrees, and the Angle of the X-axis will be greater than 180 degrees. The detailed principle please Baidu Euler Angle and attitude of the relevant information.
- 3. Since the three axes are coupled, they only exhibit independent changes when the Angle is small, and the attitude Angle will change coupled when the Angle is large. For example, when the Y-axis is close to 90 degrees, even if the attitude only rotates around the Y-axis, the Angle of the X-axis will also change greatly, which is the inherent characteristic of the attitude represented by Euler Angle.

#### Description:

- 1. The data is sent in hexadecimal not ASCII code.
- 2. Each data is transmitted in order of low byte and high byte, and the two are combined into a signed short type data. For example, the X-axis acceleration data Ax, where AxL is the low byte and AxH is the high byte. The conversion method is as follows:

#### For example:

Assuming that Data is actual data, DataH is the high byte part, and DataL is the low byte part, then: Data = ((short) DataH << 8) | DataL. It must be noted here that DataH needs to be converted to a signed short data first and then shifted, and the data type of Data is also a signed short type, so that it can represent negative numbers.



# **6.1.2 Single Return Register Data Packet**

Single return data packet needs to send register instruction first:

--XX is register number. The register number please refer to 7.3. Example as below:

Function	Instruction
Read Magnetic Field	FF AA 27 3A 00
Read Quaternion	FF AA 27 51 00
Read Temperature	FF AA 27 40 00
Read the amount of electricity	FF AA 27 64 00

After sending the instructions, the sensor will turn back a data packet 0x55 0x71. There are register addresses and 7 registers data (Fixed upload 8 registers). Return data format as below:

Start register(2 byte) + register data(16 byte, 8 registers)

		Start	Start	Start	Start	 No.8	No.8
Packet	Sign	register	register	(No.1)	(No.1)	register	register
header		low byte	high	register	register	data	data
			byte	data	data	low	high
				low byte	high byte	byte	byte
0x55	0x71	RegL	RegH	0×NN	0xNN	 0xNN	0xNN

Note: 0xNN is the specific value received, with the low byte first and the high byte second.



## **6.1.2.1 Magnetic Field Output**

Calculated formular: Unit: mG

Magnetic field (x axis) Hx=((HxH<<8)|HxL)Magnetic field (y axis) Hy=((HyH<<8)|HyL)

Magnetic field (z axis) Hz =(( HzH<<8)| HzL)

For example: Send instruction to read magnetic field in APP: FF AA 27 3A 00 (Please refer to 6.1.2)

The sensor return data to APP: 55, 71 00 68 01 00 69 3 a 7 a 00 00 00 00 00 00 00 00 00 00 00, a total of 20 bytes.

Calculate the no.5 to no.10 bytes as described above, magnetic field x=360, y=105, z=122

## 6.1.2.2 Quaternion Output

0x55   0x71   0x51   0x00   Q0L   Q0H   Q1L   Q1H   Q2L   Q2H   Q3L   Q3H		0x55	0x71	0x51	0x00	Q0L	Q0H	Q1L	Q1H	Q2L	Q2H	Q3L	Q3H
---	--	------	------	------	------	-----	-----	-----	-----	-----	-----	-----	-----

#### Calculated formular:

Q0 = ((Q0H < < 8)|Q0L)/32768

Q1=((Q1H<<8)|Q1L)/32768

Q2=((Q2H < < 8)|Q2L)/32768

Q3=((Q3H<<8)|Q3L)/32768

#### Checksum:

Sum = 0x55 + 0x59 + Q0L + Q0H + Q1L + Q1H + Q2L + Q2H + Q3L + Q3H



# **6.1.2.3 Temperature Output**

0x55 0x71 0x40	0x00 TL	TH	
----------------	---------	----	--

Calculated formular:

T=((TH<<8)|TL) /100℃



### 6.2 Commands

# **6.2.1 Read Register Value**

FF AA 27 XX 00 Read register value	
------------------------------------	--

--XX is register.

For example::

Read magnetic field: FF AA 27 3A 00 Read quaternion: FF AA 27 51 00 Read temperature: FF AA 27 40 00

After sending this instruction, the sensor will send back a data packet starting with  $0x55\ 0x71$ , which contains the data of the corresponding start register address, the start register address and the following 7 registers (8 registers are fixed to be uploaded). The format of the return data is referred to 7.1.2.

### 6.2.2 Calibration

FF AA 01 01 00	Accelerometer Calibration
FF AA 01 07 00	Magnetic Field Calibration
FF AA 01 00 00	Complete Magnetic Field Calibration

For example, to calibrate the magnetic field,

Step 1. Send FF AA 01 07 00

Step 2. Rotate the sensor 360 degree around three axis (it is recommended to rotate 3 circle, 360 degree \*3)

Step 3. Send FF AA 01 00 00 to quit the calibration



## **6.2.3 Save Settings**

FF A	A 00	SAVE	00	Save Settings
	,	O,	00	Jave Settings

SAVE: Set

0: Save current configuration

1: Restore default configuration and save

### 6.2.4 Return Rate

RATE: return rate

0x01: 0.2Hz

0x02: 0.5Hz

0x03: 1Hz

0x04: 2Hz

0x05: 5Hz

0x06: 10Hz(default)

0x07: 20Hz

0x08: 50Hz

0x09: 100Hz

0x0B: 200Hz

0x0C: Single return

#### 6.2.4 Return Rate

FF AA 27 64 00	Reading sensor power
1. 7.1. 27 0. 00	reading sensor porrer

The two data of 72 and 01 represent electric quantity, which is 0172 when converted into hexadecimal number, indicating that the voltage is 3.70v, indicating that the corresponding electric quantity is about 55%.

The decimal number corresponds to the following:

410 is 100%.

365 is 50%.

Below 320, 0%



# **6.3 Register Address**

Address	Symbol	Function
0x00	SAVE	Save the current configuration
0x01	CALSW	The calibration
0x03	RATE	Data return rate
0x05	AXOFFSET	The X-axis acceleration is zero
		partial
0x06	AYOFFSET	The Y-axis acceleration is zero
		offset
0x07	AZOFFSET	The z-axis acceleration is zero
		offset
0x08	GXOFFSET	The X-axis angular velocity is
		zero offset
0x09	GYOFFSET	The Y-axis angular velocity is zero
		offset
0x0a	GZOFFSET	The Z axis angular velocity is zero
		offset
0x0b	HXOFFSET	The X-axis magnetic field is zero
		offset
0x0c	HYOFFSET	Y-axis magnetic field zero deviation
0x0d	HZOFFSET	Z-axis magnetic field zero
		deviation
0x30	YYMM	Year and month
0x31	DDHH	Day and hour
0x32	MMSS	Minutes, seconds
0x33	MS	ms
0x34	AX	X axis acceleration
0x35	AY	Y-axis acceleration
0x36	AZ	Z axis acceleration
0x37	GX	X angular velocity
0x38	GY	Y-axis angular velocity
0x39	GZ	Z axis angular velocity
0x3a	HX	X-axis magnetic field
0x3b	HY	Y-axis magnetic field
0x3c	HZ	Z axis magnetic field
0x3d	Roll	X axis Angle
0x3e	Pitch	Y axis Angle



0x3f	Yaw	Z axis Angle
0x51	Q0	Four elements Q0
0x52	Q1	Four elements Q1
0x53	Q2	Four element Q2
0x54	Q3	Four elements Q3