

Conditions for Paralleling

- The line voltage ratio of the transformers must be same.
- The transformers should have equal per unit impedance.
- The transformers should have the same polarity.
- There should not be any phase difference between the secondary line voltages of all the transformers.
- The phase sequence of secondary line voltages of all the transformers should be same.