

13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PO Number:

CUSTOMER INFORMATION

Name: NOAA PMEL - PACIFIC MARINE ENVIRO LAB

Account: 40279844 DAVID STRAUSZ

DAVID.STRAUSZ@NOAA.GOV

206-526-4510

Bill To Address

7600 SAND POINT WAY NE

SEATTLE, WA, 98115-6349, US

Ship To Address SUPPLY CENTER / RECEIVING 7600 SAND POINT WAY NE, BLDG 8 SEATTLE,WA,98115,US

DUE TO THE LOCAL COVID-19 ISSUES ONLY DIGITAL COPIES WILL BE PROVIDED.

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM39602-4078

Special Notes

Services Requested:

PCAL37 SERVICE37

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.

Performed pressure calibration.

Performed "POST" cruise calibration.

Cleaned and replatinized the conductivity cell.

Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Unb	illed	Items
-----	-------	-------



Sea-Bird Electronics, Inc. 13431 NE 20th Street Bellevue, WA 98005 United States

Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date **Sales Order**

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1869

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2331

Special Notes
Services Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States

Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM26834-2026

Special NotesServices Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM26834-2025

Special Notes
Services Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1853

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1865

Special NotesServices Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2336

Special Notes
Services Requested:
PCAL37
SERVICE37

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:
Perform initial diagnostic evaluation.
Performed pressure calibration.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25429-1805

Special NotesServices Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2327

Special NotesServices Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if	1
	necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair".	
	Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2322

Special Notes
Services Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM36048-3770

Special Notes
Services Requested:
PCAL37
SERVICE37

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed pressure calibration.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM23834-2023

Special NotesServices Requested:

SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

Hardware was found to be seized in the end cap

Services Performed: Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the end cap. Replaced the O-rings.

Performed a hydrostatic pressure test.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
231456	fro - MODULAR uCAT SENSOR EC, W/O PRESSURE	1



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25429-1804

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

> 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM36048-3765

Special Notes
Services Requested:
PCAL37
SERVICE37

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:
Perform initial diagnostic evaluation.
Performed pressure calibration.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

Service Request Date

www.seabird.com

Phone

Sales Order

1005513079 02-JUN-2021 316433924

+1-425-643-9866

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM28082-2333

Special Notes
Services Requested:
PCAL37
SERVICE37

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:
Perform initial diagnostic evaluation.
Performed pressure calibration.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.
Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

 Service Request
 1005513079

 Date
 02-JUN-2021

 Sales Order
 316433924

SERVICE REPORT

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM29475-2355

Special Notes Services Requested: PCAL37 SERVICE37

Services Performed:
Perform initial diagnostic evaluation.
Performed pressure calibration.
Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	Extra charge to calibrate SBE 37 pressure channel	1
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

•		
Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com 1005513079

02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25541-1858

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM24246-1678

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005513079 02-JUN-2021 316433924

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: 37SM.LEGACY

Item Description: (LEGACY) SBE 37SM MicroCAT

Serial: 37SM25429-1806

Special Notes Services Requested: SERVICE37

CUSTOMER NOTES: 2025 and 1858 Cannot output salinity. Might need firmware upgrade.

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Cleaned and replatinized the conductivity cell.
Performed a "Final" Calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE37	Complete External Inspection. Test All Functions. Calibrate C & T, C&P and recal if necessary. Replace end cap O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	2

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2