The temperature probe was replaced.

Temperature Calibration Report

Customer:	Pacific Marine E	nvironmental Lab	
Job Number:	65422	Date of Re	port: 9/15/2011
Model Number	SBE 39	Serial Num	1ber: 3939602-1805
If the calibration is calibration is not possible. An 'as received' can must choose wheth during deployment allows a small corr	lentifies a problem, the erformed if the sensor libration certificate is per the 'as received' cali. In SEASOFT enter the ction for drift between pair apply only to subse	is damaged or non-functional, or by cu provided, listing coefficients to convert s bration or the previous calibration beta the chosen coefficients using the progra a calibrations (consult the SEASOFT management data.	ter work is completed. The 'as received' astomer request. Sensor frequency to temperature. Users the represents the sensor condition am SEACON. The coefficient 'offset'
Comments:	_		
	probe was found to	be bent.	
'CALIBRATION	AFTER REPAIR'	✓ P	erformed
Date: 9/15/2011]	Drift since Last cal:	N/A Degrees Celsius/yea
Comments:			