The temperature probe was replaced.

Temperature Calibration Report

Customer:	Pacific Marine Er	nvironmental Lab		
Job Number:	65422	Date of Repo	ort:	9/13/2011
Model Number	SBE 39	Serial Numb	er:	3928082-0992
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request. An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients using the program SEACON. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data. 'AS RECEIVED CALIBRATION' Performed Not Performed				
Date: 8/18/2011	J	Drift since last cal:	+0.00007	Degrees Celsius/year
Comments:				
The temperature	probe was found to	be bent.		
'CALIBRATION	AFTER REPAIR'	✓ Per	formed	□ Not Performed
Date: 9/13/2011]	Drift since Last cal:	N/A	Degrees Celsius/year
Comments:				