NOV 19 '98 Ø3:21PM GENERAL (%) ELECTRIC 68A944P.34 CONT ON SHEET FL. TITLE TEST SPECIFICATIONS 68A944394 REV. LOGIC AND STATIC ICC FIRST MADE FOR 1C3600TRLM1 CONT ON SHEET FL. SH NO. REVISIONS Ims LONGER 2. CHECK TIME DELAYS A. WITH SI TO NEG. REF AND S2 AND S3 CLOSED, APPLY 5V PEAK TO PEAK, 60 HZ SQUARE WAVE TO PIN 4 WITH RESPECT TO PIN 51. USE DUAL CHANNEL SCOPE TO MEASURE TIME DELAY BETWEEN TRAILING EDGE OF INPUT PULSE AND RISING EDGE OF OUTPUT PULSE AT PIN 40. PULSE AT PIN 40 MUST STAY NEGATIVE FOR IMS - .3 MS.AFTER INPUT PULSE HAS GONE NEGATIVE. [28] B. CLOSE SWITCH SI TO PIN 48 AND CONNECT WAVE TEK OUTPUT TO PIN 6. TIME DELAY BETWEEN FALLING PULSE AT PIN 6 AND RISING PULSE AT PIN 38 MUST BE 1 MS 2 .3 MS. C. REMOVE WAVE TEK, SET DC REF. TO 20V AND MOMENTARILY APPLY REF. TO PIN 4. USE SCOPE TO DETERMINE THAT VOLTAGE AT PIN 48 REDUCES TO LESS THAN 1 VOLT WHEN REF. IS APPLIED AND STAYS LESS THAN I VOLT FOR AT LEAST .5 SEC., EVEN THOUGH REF. WAS ONLY MOMENTARILY APPLIED. REPEAT ABOVE TEST EXCEPT WITH INPUT REF. APPLIED TO PIN 6. NOTE: TIME DELAY STARTS TIMING OUT AS SOON AS REF. IS APPLIED SO REF. MUST BE REMOVED IN LESS THAN .5 SEC. NOTE: REMOVE #67V POWER AND AC REFERENCER BEFORE INSERTING OR REMOVING CARD FROM TEST FIXTURE. \* SEE MOTES PGA 1336

GARY HARRIS

ISSUED

2-2/-72

+

Jarvinea.

\_ industry control\_ salem\_ virginia 11 OR 68

68 A 9 4 4 3 9 4

LOCATION CONT ON SHEET FL. SH NO. 2

25≵⊲

PRINTS TO

FF-603-WF (11-69)

## S TECHNOTES &



nt year de de jan in . Point de "de le lancon	162	RC35										
	163	- MV35	steement is several brooking in						*			
	ICY	- Mc83 C		-12	T. C. A	£ 6						
	(C Y	-may6	ĺ		TYA	·						
e seguine e l'esper e escuir e samer, que para e	10 S	-negy 6										
	166	- MUSY 4		1								
per a recent contract and a	NEW CONTRACTOR OF THE P	医皮肤 化二氯化物 医电影 化二氯甲基 化二氯甲基 化二氯甲基 化二氯甲基	a nahyayiddayla		110000000000000000000000000000000000000		Charles and the first of	200		e al an employ in a decision of	September 1985	 

HAVE HAD SEVERAL CARDS WITH INCORRECT LOGIC ON THE FIRST STEP OF THE CHART OF STEPT, MAINLY INVOLVING PINC 37,38 AND 39, 40. THESE WERE TRACED TO BAD CONNECTIONS ON THE THRU THE BOARD" CONNECTIONS UNDER U2 - U6. RECOLDERING THE EYELETS UNDER THE ICE RESTORES THE CARD TO CORRECT OPERATION. 9-13-01 046

ON SOME CARDS THE VOLTS INPUT IN STEP 26 MUST BE 200 AT PIN 4 OR PIN 6. AN OPEN CIRCUIT SETTING OF THE JOK TEST DOT TO DOU WELL DOOR VOLTS TO 16 OR SO AND THE CIRCUIT WILL MOT TELP TO LOWER FIN 49 TO ZERO.

TECHNICIAN:	DATE: