g		GE Industri	GE Industrial Systems		Functional Testing Specification			
	Renewal Ser Louisville,K`		LOU-GED-193X218xx					
Test Procedure for a 193X218ACG01 Pulse Transformer Card								
DOCUM	MENT REVISION STATUS	3: Determined by the last e	ntry in the "REV" a	nd "DATE" colu	mn			
REV.		DESCRIPTION			SIGNATURE	REV. DATE		
Α	Initial release				Dan Laemmle	10/10/2002		
В								
С								
© COPY	YRIGHT GENERAL ELECT	TRIC COMPANY						
PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.								
	RED BY aemmle	REVIEWED BY	REVIEWE	D BY	QUALITY APP	PROVAL Dunll		
DATE 10/10/	/2002	DATE	DATE		DATE 11/04/02			

	g	
LOU- REV. A	GE Industrial Systems Renewal Services Louisville, KY	Page 2 of 3

Functional test procedure for 193X218ACG01

1. SCOPE

1.1 This is a functional testing procedure for a 193X218ACG01 Pulse Transformer Card

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.2.1.1

4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED


5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description	
1		Oscilloscope Tektronix 2215 (or equiv)	
1		Firing Box	

	g	
LOU-	GE Industrial Systems	Page 3 of 3
REV. A	Renewal Services	
	Louisville, KY	

6. TESTING PROCESS

- 6.1 Setup
 - 6.1.1
- 6.2 Testing Procedure
 - 6.2.1 Connect +20 volts to terminal A, Com to terminal B. Connect Scope probe to terminal AG, com to AC. Connect positive non-isolated boost pulses to terminal DA, com to terminal HA. With equipment on, see pulse train. Increase scope time base to see an individual pulse as in Fig. 1.
 - 6.2.2 Move scope probe to terminal BG, com to BC. Move firing pulses to terminal DB, com to terminal HB. See pulses as in step 6.2.1 above.



6.3 ***TEST COMPLETE ***

7. NOTES

An operational test can be performed on this unit using Test Fixture H033531 for the 193X255AAG01 Card.