Date 16/06/2026 Loco No. RL005 Cab No 2 Facing Andoom Shift Driver/s TOM - NEV (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	✓ (OK) Not OK Topped up	✓ (OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 2 Rake 2 1 Rake 3 0
Loco Comp Oil	✓ OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0415	Engine Oil	Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car M	Comp Car I		Radiator Water added(mm s/glass)
Rake 2	0550	Comp Oil	Amt Added	Amt Added		Amt Added 25 pump	Amt Added -		Amt Added	Amt Added		Amt Added
Rake 3	0917	Comp Hrs	Amt Added	Amt Added		Amt Added -	Amt Added -		Amt Added	Amt Added		Amt Added
		Next Service	16311	35132		16484	8137		18126	10985		Loco Hrs
Locomotive	0506		16500	35500		17058	9100		19000	11000		Cab Cleaned COVID
Fuel added to comp cars / Loco			Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled
			Ltr's	203 Ltr's		36 Ltr's	145 Ltr's		Ltr's	Ltr's		499365
												1900 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0428		501	0557	N		1		
2	0632		750	0803	N		2		
3	0836		0925	0938	N		3	change loco vigo ok	
4	1013		1102	1108	N		1		
5	1143		1219	1232	N		2	LP Rake Mover Trouble	
6	1307	1348	1425	1430	N		3		
7	1505		1547	1626	N		1		
8	1701						2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0700	WATER/OIL LEAK Observers side 2End on footplate		
0845	change loco		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....