Date 10/9/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Steve, Jeo, Pete Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(Ok) Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N	Rake 2 Y N	Rake 3 Y N	Rake 1	Rake 2	Rake 3

Loco Comp Oil	OK Not OK Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken		Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs										Loco Hrs
	Next Service										Cab Cleaned COVID
Locomotive		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	1609		1645	1710			1		SFW
2	1745		1817	1837			2		SFW
3	1912		1943	1958			3		SFW
4	2033		2103	2120			1		
5	2155		2230	2300	No		2		
6	2335		0021	0033	No		3	Loco fuel 3000L	
7	0108		0338	0202	No		1		
8	0237		0307	0342	No		2		
9	0427						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....