Date 26/07/26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s Gary Trudi (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up 1/4	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car 1	Comp Car N		Comp Car P	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0600 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0340 / Comp Oil										
Rake 3 0445 / Comp Hrs	11315	35938		17036	8339		16661	19446		Loco Hrs 25378
Next Service	12000	36800		17057	9100		17500	19000		Cab Cleaned COVID
Locomotive 0350 / Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 512979
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0325		0408	0408	NO		2		
2	0441	0448	0517	0529	NO		3		
3	0602		0635	0646	NO		1		GH DR
4	0719		0750	0800	NO		2		GH DR
5	0833	0906		0936	Yes		3	AF6 issues	GH DR
6	1009		1039	1108	NO		1		
7	1142		1215	1219	NO		2	R7 retrieve wagon Andoom load ramp	
8	1253	1255	1322	1339	NO		3		
9	1413		1435	1453	NO		1		
10	1529								
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....