Date 27 / 2 / 26 Loco No. R1067 Cab No 2 Facing Andoom Shift Driver/s ADAM TRUDI Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 (1) Rake 2 (0) Rake 3 (3)
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Comp Car Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive	1945		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running	Loco Km's Travelled 488298.5 km
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	1500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1225		1612	1640	N		3		
2	1715		1758	1827	N		1		
3	1902		1944	2050	N		2		
4	2125		2200	2248	N		3		
5	2323		0005	0021	N		1		
6	0055		0128	0202	N		2		
7	0236						3	fuel loco	
8							1		
9							2		
10							3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....