Date 09/01/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s STEVE JED Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Comp Car	Comp Car / Comp Car	Comp Car / Comp Car	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added
Rake 3		Comp Hrs				Loco Hrs 22072
		Next Service				Cab Cleaned COVID
Locomotive	2012		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 451962
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1617	1730		1802	YES		3	EW Down	
2	1837		1910	1940	NO		1		
3	2015		2049	2058	NO		2		
4	2133		2206	2222	NO		3		
5	2257		2335	2340	N		1		
6	0015	0034	0105	0115	N		2		
7	0150		0219	0230			3		
8	0305		0336	0345			1		
9	0420						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Rake 2 Comp O Not going into Load or dump swap over to Comp I (AUTO VALVE LEAKING ALL THE TIME)		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature: .....