Date 9/2/26 Loco No. R005 Cab No 1 Facing Andoom Shift Driver/s Trudi Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil: OK / Not OK / Topped Up

Record time comp-car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car N	Comp Car K		Comp Car P	Comp Car O		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0737	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0434	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0540	Comp Hrs	35062	7247		15547	32800		10117	17384		Loco Hrs 22735
		Next Service	35000	8100		16000	33500		11000	18137		Cab Cleaned COVID
Locomotive	0444		Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running		Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running		Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running		Loco Km's Travelled 465473
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0345		0420	0444	N		2	LP RM trip - electrician called	
2	0518	0534	0604	0629	N		3		
3	0703		0736	0814	N		1		+ wisp
4	0848	0937	1010	1016	N		2	LP dump delay - trip in sub SD4	
5	1051	1104	1200	1248	N		3	Crew breaks 11-1120. Andoom slow - trip/ dumping slow. overflow	+ wisp
6	1322		1405	1450	N		1		
7	1524						2		
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Track maint (W) boards 14K + 15K. Crack fixed. No more restrictions/w boards		
	Dynamic Brake still malfunctioning		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....