Date 20/2/26 Loco No. A1007 Cab No 2 Facing Andoom Shift Driver/s Neville Adam (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(Ok) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 2 Rake 2 0 Rake 3 0
Loco Comp Oil ?	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car I	Comp Car N		Comp Car P	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0415	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0445	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0605	Comp Hrs	11262	35895		16983	8291		16612	18396		Loco Hrs
		Next Service	12000	36800		17057	9100		17500	19000		Cab Cleaned COVID
Locomotive	0415		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running		Loco Km's Travelled 515563
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2960 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0333		0409	0423	NO		1		
2	0458	0506		0543	NO		2	M/c R2	
3	0619	0655		0722	NO		3	Stacker Move LP R3	
4	0758	0808		0847			1	R1	
5	0923	0945	1053	1053	Y		2	Unload Trouble R2, compressor K	
6	1128		1203	1223	N		3		
7	1258		1342	1348	N		1		
8	1423		1518	1518	Y		2	2900L FUEL, COMP car K	
9	1553						3		
10							1		
11							2		
12							3		

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 20 7 26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Rob Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3

Loco Comp Oil	OK (Not OK) Topped Up	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs
		Next Service							Cab Cleaned COVID
Locomotive	1632		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 515700
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1553		1632	1656			3	MCR3	RR AK
2	1732		1813	1818			1	Repair Comp K R2 MCR1	RR AK
3	1854		1927	1941			2	Low Gov oil pres fault MCR2	RR CW
4	2017		2050	2102			3		
5	2138		2211	2221			1		
6	2257		2332	2343			2		
7	0019		0133	0144			3	Meal Break/One stop	
8	0220		0254	0306			1		
9	0342						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Loco needs comp oil		
	Low Gov oil presure fault E03E cleared ok oil seems		
	Ok		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....