Date 23/7/26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Jed/Steve (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car I	Comp Car IV		Comp Car GP	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added 20	Amt Added		Amt Added	Amt Added 10		Amt Added
Rake 1 0859 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0628 / Comp Oil	Comp Hrs 11315	35895		16988	8339		16612	28446		Loco Hrs 25309
Rake 3 3745 / Comp Hrs	Next Service 12000	36800		17057	9100		17500	19000		Cab Cleaned COVID
Next Service	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 511320
Locomotive 0633	Fuel added to comp cars / Loco 205 Ltr's	4 Ltr's		109 Ltr's	128 Ltr's		0 Ltr's	226 Ltr's		2300 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0401		0431	0440	No		3		
2	0515		0546	0555	No		1		SJH
3	0630			0710	Yes	8mins	2	Comp Servicing	SJH
4	0745	0748	0821	0834	No		3		SJH
5	0909		1010	1055	No		1	Loco Fuel 2300L	
6	1130		1257	1257	Y		2	2 CAR CAR HANGUPS (WASH IN PRODUCT	
7	1332.	1410	—	1455	Y	-	3	& STACKER BLOCKING GP	
8	1530						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Ditch Not Working (lights)		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....