Date 12/01/25 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s ADAM / TRUDY Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	60% Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0501	Engine Oil	Comp Car N	Comp Car J		Comp Car I	Comp Car O		Comp Car K	Comp Car P		Radiator Water added(mm s/glass)
Rake 2	0609	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0756	Comp Hrs	34806	15403		10003	32702		7077	15197		Loco Hrs 22134
		Next Service	35000	15500		10000	33500		7001	16000		Cab Cleaned COVID
Locomotive	1009		Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Running in Auto / Manual / Not Running	Running in Auto / Manual / Not Running		Loco Km's Travelled 453589
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0325		0401	0425	N		3		
2	450		0529	0546	N		1		
3	0623		0700	0720	N		2		
4	0755		0836	0851	N		3		
5	0926		1002	1029	N		i	Drivers doing rake changes Andoom	
6	1103		1138	1212	N		2	fuel loco	
7	1246		1421	1421	Y	7 mins *	3	wshop check cct - leave P off use K	
8	1455		1528				i	*(also Andoom slowing for power works)	
9								Andoom Mayday stop	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Compressor P wouldn't start problems not fixed Rake 3		
	wind speed detection on MRB still faulty - wildly inaccurate readings		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....