Date 13/5/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Garry - TRUDI Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken

		Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1	Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass)
Rake 2	Comp Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Amt Added 520
Rake 3	Comp Hrs				Amt Added
	Next Service				Loco Hrs
Locomotive 1945		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Cab Cleaned COVID
Fuel added to comp cars / Loco		Ltr's Ltr's	Ltr's Ltr's	Ltr's Ltr's	Loco Km's Travelled 498369
					1500 + 1450 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1447		1602	1645	NO		2	shunt bad wagon 2013	+ C2
2	1718		1748	1950	NO		3		2
3	2023		2100	2225	NO		1		2
4	2300		2341	0117	NO		2		
5	0151		0230	0349	NO		3	fuel loco	
6	0423						1		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	2013 OUT 205 T in		
	#2 end A/C intermitent ~~NOT cooling~~ blowing hot air (IT IS NOT THE REVERSER)		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....