Date 21/5/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Gary/Trudi/mo Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	OK Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car J	Comp Car O		Comp Car P	Comp Car N		Comp Car M	Comp Car I		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added 20	Amt Added 20		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0655 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0340 / Comp Oil										
Rake 3 0520 / Comp Hrs	16726	32985		16385	35697		17981	10917		Loco Hrs
Next Service	16500	33500		17057	36052		19000	11000		Cab Cleaned COVID
Locomotive 0550	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Loco Km's Travelled 499718
Fuel added to comp cars / Loco	168 Ltr's	70 Ltr's		240 Ltr's	Ltr's		Ltr's	257 Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0345		0417	0456	NO		2	Fuel comp cars.	
2	0529		0612	0654	NO		3	" " "	
3	0727	0900	0825	0830	NO		1	" " " Telemitry issues.	
4	0903		0941	0951	NO		2		
5	1026		1111	1122	NO		3		
6	1156		1234	1249	No		1		
7	1323		1359	1422	No		2		
8	1456		1540	1551	No		3		
9	1625						1		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	RK2 Comp N isolation Switch seized.		
0738	RK1 Comp J Telemitry not working		
	EDC/W boards MRB(South)		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....