Date 24.7.26 Loco No. 5 Cab No 1 Facing Andoom Shift Driver/s Gary / Trudi (Day) Night Shift

**The following checks are to be performed at shift handover or close as practical**

| Vigilance Operational | Engine Oil | Radiator Water | End of Rake Marker Operational | Rake Leakage Check kPa |
|---|---|---|---|---|
| (Yes) No | (Ok) Not OK Topped up | (OK) Not Ok Topped Up | Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N | Rake 1 0 Rake 2 0 Rake 3 0 |

Loco Comp Oil (OK) Not OK Topped Up

| Record time comp car/loco hrs taken | | | Lead | Rake1 | 2nd | Lead | Rake2 | 2nd | Lead | Rake3 | 2nd | Locomotive |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Comp Car L | Comp Car N | | Comp Car P | Comp Car K | | Comp Car J | Comp Car M | | Radiator Water added(mm s/glass) |
| Rake 1 | 0340 | Engine Oil | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 2 | 0455 | Comp Oil | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added | Amt Added | | Amt Added |
| Rake 3 | | Comp Hrs | 11315 | 35906 | | 17005 | 8339 | | 16629 | 19446 | | Loco Hrs 25330 |
| | | Next Service | 12000 | 36500 | | 17057 | 9100 | | 17500 | 19000 | | Cab Cleaned COVID |
| Locomotive | 0330 | | Running in Auto / Manual (Not Running) | Running in Auto / Manual Not Running | | Running In Auto/ Manual Not Running | Running in Auto / Manual (Not Running) | | Running In Auto / Manual Not Running | Running In Auto / Manual (Not Running) | | Loco Km's Travelled 511888 |
| Fuel added to comp cars / Loco | | | Ltr's | Ltr's | | Ltr's | Ltr's | | Ltr's | Ltr's | | 3500 Ltrs |

| Trip No | Dump Station Arrival Time | Dump Station Green Light | Load Station Arrival Time | Load Station Green Light | Delay to Production Yes / No | Delay Time minutes | Rake No | Reason for Delay | Manual Brake Pipe Continuity Completed (Train Drivers Initials Required) |
|---|---|---|---|---|---|---|---|---|---|
| 1 | 0333 | 0335 | 0410 | 0421 | NO | | 1 | | |
| 2 | 0454 | | | 0535 | | | 2 | Fuel loco 2000L | |
| 3 | 0608 | | 0710 | 0802 | NO | | 3 | Andoom down 1500L | GH R |
| 4 | 0835 | | 1245 | 1302 | NO | | 1 | Tailings flush. | R + WShop GH |
| 5 | 1336 | | 1404 | 1416 | NO | | 2 | | R GH |
| 6 | 1450 | | 1518 | 1530 | NO | | 3 | ~~Shunt R2~~ | |
| 7 | 1604 | | | | | | | | |
| 8 | | | | | | | | | |
| 9 | | | | | | | | | |
| 10 | | | | | | | | | |
| 11 | | | | | | | | | |
| 12 | | | | | | | | | |

| Time of Fault/Delay | Fault/Delay Description | Notification Raised | Notification No. |
|---|---|---|---|
| | RK1 Shunt 2065 out 2013 in | | |
| | Rk2 Shunt 2082 + 2050 out - 2043+2078 IN | | |
| | | | |

**A Continuity Test must be done before moving the Train after Rake changeover!**

*Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....*