Date 01 / 01 / 2026 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s TRUDI Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	OK Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 1 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
Rake 1	0406	Engine Oil	Comp Car N Amt Added	Comp Car J Amt Added	Comp Car I Amt Added	Comp Car M Amt Added	Comp Car K Amt Added	Comp Car P Amt Added	Radiator Water added(mm s/glass) Amt Added
Rake 2	0547	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs	34739	15288	9995	17020			Loco Hrs 21865
		Next Service	35000	15500	10000	17000			Cab Cleaned COVID
Locomotive	0441		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 446651
Fuel added to comp cars / Loco			Ltr's	Ltr's	50 Ltr's	Ltr's	Ltr's	Ltr's	2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0410		0509	0509	Y		1	fuel loco / crew swap / swap CC	R + AR
2	0543		0946	0957	N		2	swap CC + fuel	Z + AR
3	1031		1114	1118	Y (2m partial)		3	Shunt R3 IN : 66 OUT: 107	Z + wshop.
4	1152	1154	1222	1239	N		1	[0545 FLUSH 2-3 HRS]	
5	1313		1415		Y		2	Crew break 30 mins x 2	
6	1450						3	Dump stn delay - faulty wagon 66 fuel CC K	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Radio: No 1 end faulty - workshop aware		
	Telemetry slow to respond to applications R2 + R1		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....