Date 1/6/26 Loco No. R1025 Cab No 2 Facing Andoom Shift Driver/s GARY TRUDI Day ~~Night~~ Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up V30	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0800 — Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0500 — Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Loco Hrs 24588
Rake 3 0516 — Comp Hrs	16766	33035		16412	8059		10934	18031		Cab Cleaned COVID
Next Service	16500	33500		17057	9100		11060	19000		Loco Km's Travelled 464326
Locomotive 0430	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		(Running) in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		(Running) in Auto / Manual Not Running	Running in Auto / Manual (Not Running)		
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0336	0426	0456	0520	NO		2		GH JK
2	0553		0630	0708	NO		3		GH JK
3	0740		0810	0858	NO		1		GH JK
4	0930	1022	1052		NO		2	AIR LEAK between 100 + 25??	
5			1220	1249	NO		3		
6	1324		1401	1440	NO		1	Dump stn delays: C2 blocked	
7	1315						2	↑ ↑	
8							3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	AIR LEAK R2 100/25 wagons. WShop to inspect. Not impacting production		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....