Date 18/10/26 Loco No. R1085 Cab No 2 Facing Andoom Shift Driver/s Steve-Pete-Jed Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up +40	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken

		Engine Oil	Comp Oil	Comp Hrs	Next Service
Rake 1					
Rake 2					
Rake 3					
Locomotive					

Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
									Loco Hrs
									Cab Cleaned COVID
Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled
Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1900 Ltrs

Fuel added to comp cars / Loco

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1541		1630	1748	Y		2	ANDOOM PROBLEMS	SGM
2	1823		1900	2218	Y		3	" "	SGM
3	2253	0227		0307	Y		1	REFUEL (LORIM POINT PROBLEMS)	SGM
4	0342						2		
5							3		
6									
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R1 Rolling on @ andoom swapped Comp P4M		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....