Date 19 / 02 / 26 Loco No. R1005 Cab No 1 Facing Andoom Shift Driver/s GARY NEVILLE (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

	Record time comp car/loco hrs taken		Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car J		Comp Car K	Comp Car P		Comp Car O	Comp Car I		Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0825	Engine Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added 20 pumps		Amt Added	Amt Added
Rake 2	0350	Comp Oil	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3	0615	Comp Hrs	15500		7406	15711		32800	10240		17419	Loco Hrs 22947
		Next Service	16500		8100	16000		33500	11000		18137	Cab Cleaned COVID
Locomotive	0400		Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)		Running in Auto / Manual (Not Running)	Loco Km's Travelled 469464
Fuel added to comp cars / Loco			Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0547		0420	0540	NO		2		
2	0613		0646	0750	NO		3		GH AN
3	0823		0855	1011	NO		1		GH AN
4	1044		1123	1238			2		AN
5	1313		1349	1444			3		
6	1519						1	fuel loco	
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 19/2/26 Loco No. RL005 Cab No 1 Facing Andoom Shift Driver/s ADAM / TRUDI Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	SOK Ok Not OK Topped up	OK Not Ok Topped Up		Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 1 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up	Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive

Record time comp car/loco hrs taken			Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Comp Car	Radiator Water added(mm s/glass)
Rake 1		Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs							Loco Hrs 22991
		Next Service							Cab Cleaned COVID
Locomotive	2030		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 469755
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2300L + 1300 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1519		1610	1711	No		1	2300L FUEL	
2	1746		1826	1916	No		2		JC
3	1959		2026	2120	No		3		JC
4	2155		2233	2339	N		1		JC
5	0013		0045	0136	N		2		
6	0210		0250	0336	N		3	* Gen Field switch (see below)	
7	0410						1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Dyno still not working — Will Need to come in to the Shed For Repair		
	Gen Field switch Cab 2 - need to adjust as it registers off when its ON (up) Jiggle fixes it.	Reported	

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....