Date 8/08/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Trudi Adam (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓66 G	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 Y N Rake 3 (Y) N	Rake 1 Ø Rake 2 Ø Rake 3 Ø
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car K	Comp Car J		Comp Car P	Comp Car N		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0342	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0550	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0707	Comp Hrs	7529	15645		15926	35117		10388	17546		Loco Hrs 23267
		Next Service	8100	16500		16000	36000		11000	18137		Cab Cleaned COVID
Locomotive	0427		Running in Auto / Manual ~~Not Running~~	~~Running in Auto~~ / Manual Not Running		Running in Auto / Manual ~~Not Running~~	~~Running in Auto~~ / Manual Not Running		~~Running in Auto~~ / Manual Not Running	Running in Auto / Manual ~~Not Running~~		Loco Km's Travelled 474765
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Ltrs

Trip No	Dump Station		Load Station		Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
	Arrival Time	Green Light	Arrival Time	Green Light					
1	0343		0425	0523	N		1		JP + JS
2	0558		0635	0742	N		2		JP
3	0818		0855	0939	N		3		JP
4	1013	1230	~~1235~~ 1237	1237	Y		1	DELAY Dumping - swapped Com J to K in Man Dump	
5	1312	1335	~~1514~~ 1515	~~1515~~			2	Shunt waggons out	
6	1550						3		
7							1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
1020	DELAY Dumping - swapped compressor car J to K put in Man Dump		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....