Date 31/5/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Gary Trud. (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓ 60	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 Ø Rake 2 Ø Rake 3 1

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car J	Comp Car O		Comp Car P	Comp Car K		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 1 0603 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0421 / Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0527 / Comp Hrs	16248	33035		163914	8059		10921	18051		Loco Hrs 24564
Next Service	16500	33500		17057	9100		11000	19000		Cab Cleaned COVID
Locomotive 0426	(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		(Running in Auto / Manual) Not Running	Running in Auto / Manual (Not Running)		(Running in Auto / Manual) Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 493987
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		2500 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0333		0412	0520	NO		2		+ JS
2	0554		0638	0750	N		3		
3	0825		0919	1005	N		1	Telemetry - not going into transit R1 screen	+ DT
4	1040		1113	1205	NO		2		
5	1234		R08	1403	NO		3		
6	1436							Fuel loco	
7									
8									
9									
10									
11									
12									

Spend Grinder

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R2 EOT not flashing (to End)		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....