Date 4/10/26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glen Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	OK Not OK Topped Up

Record time comp car/loco hrs taken			Lead Rake1 2nd		Lead Rake2 2nd		Lead Rake3 2nd		Locomotive
			Comp Car P	Comp Car V	Comp Car O	Comp Car K	Comp Car I	Comp Car M	Radiator Water added(mm s/glass)
Rake 1	0405	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 2	0455	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0625	Comp Hrs	17546	17233	33979	8816	11731	19015	Loco Hrs 26121
		Next Service	18137	17500	34500	9100	12000	19000	Cab Cleaned COVID
Locomotive	0335		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ Not Running	~~Running in Auto / Manual~~ Not Running	Running In Auto / ~~Manual~~ Not Running	Loco Km's Travelled 529677
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	3000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0310	0335	0400	0418			1	Attempted to fuel fuelpump u/s.	
2	0453		0530	0545			2		
3	0620		0655	0716			3		MC CW.
4	0751		0825	0838			1		MC VH.
5	0913		0945	1000			2		MC VH.
6	1035	11:55	1220	1220			3	Shunt Rake 3 "Mout Zin "L" is duty comp.	
7	1255		1325	1355			1		
8	14:30						2		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Shunt 10:35 - 11:00 Fuelled Loco 11:00 - 11:25		
	Meal Break 11:25 - 11:55		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....