Date 28 / 10 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Alex / Adam Day / Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y / N Rake 2 Y / N Rake 3 Y / N	Rake 1 1 Rake 2 0 Rake 3 2
Loco Comp Oil	OK / Not OK / Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car P		Comp Car	Comp Car O		Comp Car K	Comp Car 1		Comp Car L	Radiator Water added(mm s/glass)
Rake 1 0720	Engine Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added 30P		Amt Added 30P	Amt Added
Rake 2 0400	Comp Oil Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added
Rake 3	Comp Hrs 17727		19076	34109		8982	11863		166	Loco Hrs
	Next Service 18137		20000	34500		9100	12000		1001	Cab Cleaned COVID
Locomotive	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Loco Km's Travelled
Fuel added to comp cars / Loco	Ltr's		Ltr's	Ltr's		Ltr's	93 Ltr's		93 Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0427		0507	0521	N		2		AA
2	0556		0642	0646	N		3		
3	0721	0725	0808	0815	N		1	Loco oil leak check	
4	0850		0927	0943	N		2		
5	1015		1119	1119	Y		3	EOR car fault back	
6	1154		1233	1244	N		1		
7	1319		1403	1421	N		2		
8	1456						3		
9							1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Loco 5 oil leak		
	EOR car fault fixed Rake 3 / Fault back came good after tunnel		
	19 Switches Red/white twice slight gap maybe 3mm		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....