Date 15/9/24 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s Adam Nevin Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	Ok / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	OK / Not OK / Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car P	Comp Car J		Comp Car O	Comp Car K		Comp Car I	Comp Car M		Radiator Water added(mm s/gless)
Rake 1	0339	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0445	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0607	Comp Hrs	17357	17096		33857	8643		11612	18847		Loco Hrs
		Next Service	18137	17500		34500	9100		12000	19000		Cab Cleaned (Y/N)
Locomotive	0507		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		533092
												600 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0230		0330	0351	N		1		
2	0426		0504	0518	N		2		
3	0553						3	Andoom down, pump replaced	
4							1		
5							2		
6							3		
7							1		
8							2		
9							3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 15/9/21 Loco No. RT007 Cab No 2 Facing Andoom Shift Driver/s Glen Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational			Rake Leakage Check kPa		
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N	Rake 2 (Y) N	Rake 3 (Y) N	Rake 1 (5)	Rake 2 (0)	Rake 3 (1)

Loco Comp Oil			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 1		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2		Comp Hrs										Loco Hrs 7575
Rake 3		Next Service										Cab Cleaned COVID
Locomotive	2039	Fuel	Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Running In Auto / Manual Not Running	Running In Auto / Manual Not Running		Loco Km's Travelled 533155
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		700 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0053		1800	1952			3	Andoom down	
2	2027		2100	2117			1		
3	2155		2250	2238			2		
4	2313		2340	2358			3		
5	0035		0100	0123			1		
6	0158		0230	0245			2		
7	0320						3	Rolled too.	
8							1		
9									
10								Loco Fuel 700L	
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....