Date 18/7/26 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s GARY - TRUDI Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	OK	Not OK	Topped Up

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service										Loco Hrs
Locomotive	1530		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 514364
												Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1525		1613	1635	NO		3	Fuel loco 1400L	
2	1709		1748	1800	NO		1	workshop looking at comp 1 & RK2	TR
3	1833		1903	1923	NO		2		SB
4	1956		2040	2047	NO		3		D
5	2120		2150	2206	NO		1		
6	2240		2312	2321	No		2	Need to drop air to get brakes off andoom	
7	2355		0026	0044	NO		3		
8	0118		0150	0202	NO		1		
9	0237		0325	0331	NO		2	*R2 very slow to build air * → Dump delays LP-7 still to dump on arrival	
10	0406						3		
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Engine room oil leak floor		
*	R2 has an air problem *		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....