Date 6,9,26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver's TRUDI Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	OK / Not OK / Topped up	OK / Not OK / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 4 Rake 2 0 Rake 3 0
Loco Comp Oil: OK / Not OK / Topped Up				

Record time comp car/loco hrs taken			Lead Rake1	2nd	Lead Rake2	2nd	Lead Rake3	2nd	Locomotive
			Comp Car P	Comp Car J	Comp Car O	Comp Car K	Comp Car I	Comp Car M	
Rake 1	0451	Engine Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Radiator Water added(mm e/glass) Amt Added
Rake 2	0626	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	1505	Comp Hrs	17373	17135	33873	8682	11635	18870	Loco Hrs
		Next Service	18137	17500	34500	9100	12000	19000	Cab Cleaned COVID
Locomotive	0525		Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running	Running In Auto / Manual / Not Running	Loco Km's Travelled 525840
Fuel added to rake comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0250		0409	0411			3	3200 L	
2	0445		0521	0545	NO		1		TR
3	0619		0658	0921	NO		2	Haul down 2hrs	
4	0955		1041	1049	NO		3	2x pax HR	
5	1120		1158	1215	NO		1		TR
6	1250 -		1423	1425	N/Y ?		2	1320L fuel Crew break 30 m	TR
7	1900						3	(fuel point running slow, came good)	
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	MRB (W) North end only		
	Handle broke off driver side window No 2 end		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....