Date 15/08/26 Loco No. R1005/R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM NEV (Day) Night Shift

The following checks are to be performed at shift handover or as close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil: (OK) Not OK Topped Up

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
			Comp Car P	Comp Car N		Comp Car O	Comp Car K		Comp Car J	Comp Car M		Radiator Water added(mm s/glass)
Rake 1	0804	Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	0926	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0610	Comp Hrs	17175	36114		33532	8455		16837	18590		Loco Hrs
		Next Service	18137	36800		34500	9100		17500	19000		Cab Cleaned (COVID)
Locomotive	820		Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		Running In Auto / Manual Not Running	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto (Manual) Not Running		Loco Km's Travelled
												522325.9
Fuel added to comp cars / Loco			l.tr's	l.tr's		l.tr's	l.tr's		l.tr's	l.tr's		2300 l.trs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0825		0444	0452	Y	heaps	2	Loco issues, reboot loco	
2	0528		0657	0657	Y		3	Loco swap	
3	0732	0806	0857	0857	Y		1	Delay Dumping	
4	0926		1003	1008	N		2		
5	1043		1122	1135	N		3		
6	1210		1243	1302	N		1		
7	1387		1413	1428	N		2		
8	1503		1555	1557	N		3	fuel loco	
9	1633						1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Governor oil low		
	R1 2054 flat spots		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....