Date 30/1/26 Loco No. 8005 Cab No 1 Facing Andoom Shift Driver/s Trudi / Adam Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes No	Ok Not OK Topped up	OK Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 0 Rake 2 0 Rake 3 1
Loco Comp Oil	OK Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Amt Added	Comp Car / Amt Added	Comp Car / Amt Added	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3		Comp Hrs				Loco Hrs
		Next Service				Cab Cleaned COVID
Locomotive	1820		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 22507
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	460521 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1612		1642	1708	N		2		
2	1742		1820	1903	N		3		TL
3	1937		2014	2031	N		1		TL
4	2105		2142	2200	N		2		TL
5	2234		2320	2335	N		3		
6	0010		0045	0104	N		1		
7	0139		0214	0230	N		2		
8	0305						3		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....