Date 30/09/26 Loco No. RL005 Cab No 2 Facing Andoom Shift Driver/s ADAM NEV (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 1 Rake 2 0 Rake 3 0
Loco Comp Oil	(OK) Not OK Topped Up				

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car P	Comp Car J		Comp Car O	Comp Car K		Comp Car I	Comp Car M		Radiator Water added(mm s/glass)
Rake 1 0709	Engine Oil Amt Added 30 pumps	Amt Added		Amt Added	Amt Added		Amt Added 30 pumps	Amt Added 30 pumps		Amt Added
Rake 2 0758	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3 0610	Comp Hrs 17524	17183		33946	8790		11715	18964		Loco Hrs
	Next Service 18137	17500		34500	9100		12000	19000		Cab Cleaned COVID
Locomotive 0823	(Running In Auto / Manual) Not Running	Running In Auto / Manual (Not Running)		(Running In Auto / Manual) Not Running	Running In Auto / Manual (Not Running)		(Running In Auto / Manual) Not Running	Running In Auto / Manual (Not Running)		Loco Km's Travelled 527 225
Fuel added to comp cars / Loco	111 Ltr's	75 Ltr's		Ltr's	156 Ltr's		151 Ltr's	Ltr's		2200 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0326		0408	0411	N		1		JL
2	0446		0525	0544	N		2		
3	0619		0657	0706	N		3		JL
4	0741		0819	0830	N		1		
5	0905		1019	1019	Y		2	Shunt Bad wagon	JL
6	1054		1141	1208	N		3	Fuel Loco	
7	1243		1326	1333	N		1		
8	1408		1448	1453			2		
9	1528						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0930	Rake 2 2064 out 2047 in		
	All Comps Fueled up		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

2064 2047