Date 14 / 1 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s Glen/Rob Day Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
Yes / No	OK / Not OK / Topped up	OK / Not Ok / Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 2 Rake 2 0 Rake 3 0
Loco Comp Oil: OK / Not OK / Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	0530.	Engine Oil	Comp Car N	Comp Car J		Comp Car I	Comp Car O		Comp Car K	Comp Car M		Radiator Water added(mm s/glass)
Rake 2	0725.	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0400	Comp Hrs	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
		Next Service	34834	15403		10003	32736		7107	17137		Loco Hrs 22176
Locomotive	0408.		35000	15500		10000	33500		7001	18137.		Cab Cleaned COVID
			Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		~~Running in Auto / Manual~~ Not Running	Running in Auto / ~~Manual~~ ~~Not Running~~		Running in Auto / ~~Manual~~ ~~Not Running~~	~~Running in Auto / Manual~~ Not Running		Loco Km's Travelled 454474
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1102L Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0402		0435	0511			3		
2	0546		0620	0705			1		
3	0743		0829	0854			2		MC RA
4	0930	1017	1040	1042	Y		3	Shunt Rake 3 2066 + 2044 in MC AR	
5	1117		1145	1258			1	2102 + 2080 out.	
6	1337		1442	1443	Y		2	Shunt I out Pin RZ	
7	1519		1557	1618			3	Fuel loco 1102L	
8	1654						1		
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 14 / 1 / 26 Loco No. 5 Cab No 2 Facing Andoom Shift Driver/s Gary Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water		End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up		Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0
Loco Comp Oil	OK Not OK Topped Up				

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1		Engine Oil	Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Comp Car Amt Added	Comp Car Amt Added		Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3		Comp Hrs										Amt Added
		Next Service										Loco Hrs 22192
Locomotive	1800		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Cab Cleaned COVID
Fuel added to comp cars / Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		Loco Km's Travelled 454810 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1654		1730	1750	NO		1		
2	1823	1913	1941	1946	Yes	???	2	MCR1 Loc in point. MCR2	RA
3	2019	2029	2100	2204	NO		3		RA
4	2237		2308	2340	NO				
5	0013	0300	0324	0325	Yes			Compressor Fault / operator error	
6	0358								
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	R/L2 comp 0 stopped while dumping / control failed to notice wagons were not Dumping had to pull rake Back 24 wagons to Dump.		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....