Date 05/11/26 Loco No. RL005 Cab No 2 Facing Andoom Shift Driver/s TRUDI / GARY (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up 480G	(Ok) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 0 Rake 2 0 Rake 3 0

Loco Comp Oil	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
(OK) Not OK Topped Up	Comp Car P	Comp Car M		Comp Car O	Comp Car K		Comp Car I	Comp Car L		Radiator Water added(mm s/glass)
Record time comp car/loco hrs taken	Amt Added	Amt Added 30 pumps		Amt Added —	Amt Added —		Amt Added	Amt Added		Amt Added
Rake 1 0453 / Engine Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2 0538 / Comp Oil	Comp Hrs 17742	19199		34110	9107		11952	207		Loco Hrs
Rake 3 0658 / Comp Hrs	Next Service 18137	20000		34500	9100		12000	1061		Cab Cleaned COVID
Next Service	Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Running In Auto / Manual (Not Running)	Running In Auto / Manual (Not Running)		Loco Km's Travelled 543772
Locomotive 0455	Ltr's	233 Ltr's		Ltr's	176 Ltr's		164 Ltr's	8 Ltr's		Ltrs
Fuel added to comp cars / Loco										

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0415		0450	0503	NO		1		
2	0537		0615	0624	NO		2	cc swapped (K→O) - serviced both	
3	0658		0734	0744	NO		3	cc swapped (L→I) - serviced both	
4	0818		0855	0928	NO		1	cc swapped (M→P) - serviced both	
5	1002		1035	1056	NO		2		
6	1130		1207	1216	NO		3		
7	1249		1321	1347	NO				
8	1420		1459	1513	NO				
9	1547							* WORKERS ON MRB *	
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....