Date 22/06/2026 Loco No. R1007 Cab No 2 Facing Andoom Shift Driver/s ADAM NEV (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 (Y) N Rake 2 (Y) N Rake 3 (Y) N	Rake 1 [Rake 2 O Rake 3 O
Loco Comp Oil: (OK) Not OK Topped Up				

Record time comp car/loco hrs taken			Rake1 Lead	Rake1 2nd	Rake2 Lead	Rake2 2nd	Rake3 Lead	Rake3 2nd	Locomotive
Rake 1	0653	Engine Oil	Comp Car J	Comp Car O	Comp Car P	Comp Car K	Comp Car N	Comp Car M	Radiator Water added(mm s/glass)
Rake 2	0423	Comp Oil	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added	Amt Added
Rake 3	0550	Comp Hrs	16423	33218	16630	8188	35755	18162	Loco Hrs
		Next Service	16500	33500	17057	9100	36052	19000	Cab Cleaned COVID
Locomotive	0512		Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Running in Auto / Manual (Not Running)	Running in Auto / Manual (Not Running)	Running in Auto / Manual Not Running	Loco Km's Travelled 502645
Fuel added to comp cars / Loco			Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	Ltr's	2000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0431		507	0530	N		2		
2	0605	0650	0740	0740	Y		3	Rakemover Delay Dump	
3	0815		0901	0920	N		1	Telemetry issues	
4	0955		1047	1049	Y		2		
5	1126		1203	1225	N		3		
6	1300		1351	1353	N		1	fuel Loco	
7	1428		1507	1528	N		2		
8	1603						3		
9							1		
10							2		
11							3		
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
0605-650	Rakemover Delay Dumper		
0930	Rake 1 Telemetry issues doesn't go into transit at rear		
1500	R3 Comp M manual Dump - Running but no Door Air		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....

Date 22/6/26 Loco No. R1004 Cab No 2 Facing Andoom Shift Driver/s ROB / GLEN Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

	Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Record time comp car/loco hrs taken	Comp Car	Comp Car		Comp Car	Comp Car		Comp Car	Comp Car		Radiator Water added(mm s/glass)
Rake 1	Engine Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 2	Comp Oil Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	Comp Hrs									Loco Hrs
	Next Service									Cab Cleaned COVID
Locomotive 1653	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running		Loco Km's Travelled 502943
Fuel added to comp cars / Loco	Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		1000 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1603		1650	1720			3	MC R3	RR DP
2	1756		1831	1842			1	MC R1	RR
3	1918		1953	2009			2	MC R2	RR
4	2045		2114	2130			3		
5	2206	2215	2247	2254			1		
6	2330		2405	0021			2		
7	0056	0106	0131	0146			3	fuelled loco 1000 Ltrs	
8	0221		0250	0311			1		
9	0346						2		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	Comp 0 tel issue		
	Loco governer low oil pressure fault		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....