Date 22/01/26 Loco No. R1007 Cab No 1 Facing Andoom Shift Drivers NEV (Day) Night Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(OK) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 Rake 2 Rake 3
Loco Comp Oil ?	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead	Rake1	2nd	Lead	Rake2	2nd	Lead	Rake3	2nd	Locomotive
Rake 1	1220	Engine Oil	Comp Car N Amt Added	Comp Car J Amt Added		Comp Car P Amt Added	Comp Car O Amt Added		Comp Car K Amt Added	Comp Car M Amt Added		Radiator Water added(mm s/glass) Amt Added
Rake 2	0345	Comp Oil	Amt Added	Amt Added		Amt Added	Amt Added		Amt Added	Amt Added		Amt Added
Rake 3	0850	Comp Hrs	34967	15403		15305	32753		7124	17251		Loco Hrs
		Next Service	35000	15500		16000	33500		7001	18137		Cab Cleaned COVID
Locomotive	0600		Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		Running In Auto / ~~Manual~~ ~~Not Running~~	~~Running In Auto / Manual~~ Not Running		~~Running In Auto / Manual~~ Not Running	Running In Auto / ~~Manual~~ ~~Not Running~~		Loco Km's Travelled 487620
Fuel added to comp cars/Loco			Ltr's	Ltr's		Ltr's	Ltr's		Ltr's	Ltr's		550 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	0230		0422	0429	N		1	trip + slow loading	R
2	0504		0555	0740			2		
3	0815		1440	1503			3	fuel loco, Andoom Down, one stop	DT
4	1538						1	Shunts on R1	JR
5							2		
6							3		
7									
8									
9									
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	change over Comp Cars R1 & R3 Left comp P running		
	Shunt R1 wagon 2103, 2083, 2009 out, wagon 2080 "EOR", 2012, 2107 in		
1405	Crane broken down on MRB "EOR"		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....