Date 11 / 01 / 26 Loco No. R1005 Cab No 2 Facing Andoom Shift Driver/s STEVE JED Day (Night) Shift

The following checks are to be performed at shift handover or close as practical

Vigilance Operational	Engine Oil ↓55	Radiator Water	End of Rake Marker Operational	Rake Leakage Check kPa
(Yes) No	(Ok) Not OK Topped up	(OK) Not Ok Topped Up	Rake 1 Y N Rake 2 Y N Rake 3 Y N	Rake 1 / Rake 2 / Rake 3
Loco Comp Oil	(OK) Not OK Topped Up			

Record time comp car/loco hrs taken			Lead Rake1 2nd	Lead Rake2 2nd	Lead Rake3 2nd	Locomotive
Rake 1		Engine Oil	Comp Car / Comp Car	Comp Car / Comp Car	Comp Car / Comp Car	Radiator Water added(mm s/glass)
Rake 2		Comp Oil	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added	Amt Added / Amt Added
Rake 3		Comp Hrs				Loco Hrs 22,116
		Next Service				Cab Cleaned COVID
Locomotive	16:34		Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Running in Auto / Manual Not Running	Loco Km's Travelled 453,119
Fuel added to comp cars / Loco			Ltr's / Ltr's	Ltr's / Ltr's	Ltr's / Ltr's	2206 Ltrs

Trip No	Dump Station Arrival Time	Dump Station Green Light	Load Station Arrival Time	Load Station Green Light	Delay to Production Yes / No	Delay Time minutes	Rake No	Reason for Delay	Manual Brake Pipe Continuity Completed (Train Drivers Initials Required)
1	1534		1610	1633			1		
2	1708		1742	1758			2		
3	1833		1908	1933			3		
4	2008		2038	2102			1		
5	2137		2204	2225			2		
6	2300		2334	2347			3	LOCO FUEL 2206L	
7	0027		0054	0103			1		
8	0138		0225	0245			2		
9	0325						3		
10									
11									
12									

Time of Fault/Delay	Fault/Delay Description	Notification Raised	Notification No.
	2021 FAILED TO LOAD RK3		

A Continuity Test must be done before moving the Train after Rake changeover!

Document reviewed and necessary Notifications/Maintenance Orders raised. Crewleader Signature.....