

Note: Pin1 CTRL and Pin3 GND are shortage which will pull wire cable in IMRC unit.
Controlling program please view my GitHub project of details.

