

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	19-Jun-23
Jam Berangkat	10.50 WIB
Jam Repair	13.30 S/D 16.15
Jam Kembali	19.30 WIB
Qty Unit Repair	11 pcs
Assy No	-
Type Unit	PC210 HARVESTER
Jumlah Man Power	1 Orang
Driver	1 Orang
Method Repair	Potong Wire ganti terminal dan pasang connector


Maker of Harness ☐ BEI ☒ NON BEI

Cause of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	1062-16-0122	12 Pcs
Terminal	1060-16-0122	28 pcs
Connector	DT06-6S-EP06	2 Pcs
Connector	DT04-6P-E005	2 Pcs
Retainer	W6P	2 Pcs
Retainer	W6S-P012	2 Pcs
Connector	DT04-2P-E005	8 pcs
Retainer	W2P	8 pcs
Tape	WHVTA 19*20B	400 mm


1. Modif wire harness PC210 HARVESTER sebanyak 2 pcs



2. Modif connector untuk Blower PC210 sebanyak 3 pcs



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
		
Asst Manager QA	Leader QA	Repairman