

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	26-Jun-23
Jam Berangkat	08.10 WIB
Jam Repair	10.30 S/D 15.30
Jam Kembali	18.00 WIB
Qty Unit Repair	30 pcs
Assy No	-
Type Unit	PC135F-10MO
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector


Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	30 Pcs
Rubber seal	7157-2571-80	30 Pcs
Connector	7123-6214-40	30 Pcs

1. Modif harness PC135F pada posisi AC03 dari connector DT connector 7123-6214-40 sebanyak 30 pcs



2. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman