

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	10-Aug-23
Jam Berangkat	07.50 WIB
Jam Repair	09.45 S/D 15.30
Jam Kembali	18.00 WIB
Qty Unit Repair	32 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0
Jumlah Man Power	1 Orang
Driver	---
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI




MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	32 Pcs
Rubber seal	7157-2571-80	32 Pcs
Connector	7123-6214-40	32 Pcs


1.Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 32 pcs

Before :


After :



2.Assy No



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman