

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	29-Aug-23
Jam Berangkat	07.25 WIB
Jam Repair	13.05 S/D 15.50
Jam Kembali	20.05 WIB
Qty Unit Repair	2 pcs
Assy No	-
Type Unit	PC210 HARVESTER
Jumlah Man Power	2 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI


Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Terminal	1060-16-0122	14 Pcs
Terminal	1062-16-0122	18 pcs
Connector	DT04-2P-E005	1 Pcs
Connector	DT06-6S-EP06	2 Pcs
Connector	DT04-6P-E005	2 Pcs
Retainer	W6P	2 Pcs
Retainer	W6S-P012	2 Pcs
Retainer	W2P	1 Pcs
Tape	WHVTA 19*20B	500 mm

1.Modif wire harness PC210 HARVESTER sebanyak 2 unit



Before :



After :



2.Modif connector untuk Blower PC210 HARVESTER sebanyak 1 pcs



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman