

LAPORAN REPAIR SUMITOMO INDONESIA

Tanggal Repair	14-Sep-23
Jam Berangkat	09.00 WIB
Jam Repair	10.05 S/D 10.50
Jam Kembali	- WIB
Qty Unit Repair	1 pcs
Assy No	KBR20700-E-00
Type Unit	LINK BELT
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Ganti connector

Maker of Harness ☒ BEI ☐ NON BEI


Couse of Defect ☐ BEI ☒ NON BEI

MATERIAL UNTUK REPAIR :


PART NAME	PART NO	QTY
Connector	7222-7544-40	1 Pcs

1.Ganti connector 7222-7544-40 pada assy KBR20700-E-00

Before :



After :



2.Assy no dan serial no



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman