

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	27-Sep-23
Jam Berangkat	07,30
Jam Repair	09,15 S/D 16.40
Jam Kembali	19.15 WIB
Qty Unit Repair	3 pcs
Assy No	-
Type Unit	PC210 HARVESTER
Jumlah Man Power	1 Orang
Driver	1 Orang
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Couse of Defect ☐ BEI ☒ NON BEI



MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	1060-16-0122	24 Pcs
Terminal	1062-16-0122	18 pcs
Connector	DT04-2P-E005	3 Pcs
Connector	DT06-6S-EP06	3 Pcs
Connector	DT04-6P-E005	3 Pcs
Retainer	W6P	3 Pcs
Retainer	W6S-P012	3 Pcs
Retainer	W2P	3 Pcs
Tape	WHVTA 19*20B	500 mm



1.Modif wire harness PC210 HARVESTER sebanyak 3 unit

Before :

After :



2.Modif connector untuk Blower PC210 HARVESTER sebanyak 3 pcs



3.Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman