

LAPORAN REPAIR KOMATSU INDONESIA

Tanggal Repair	19-Oct-23
Jam Berangkat	08.40 WIB
Jam Repair	11.05 S/D 16.50
Jam Kembali	19.05 WIB
Qty Unit Repair	39 pcs
Assy No	22150615-00
Type Unit	PC135F-10M0 dan PC210
Jumlah Man Power	1 Orang
Driver	-
Methode Repair	Potong Wire ganti terminal dan pasang connector

Maker of Harness ☐ BEI ☒ NON BEI

Cause of Defect ☐ BEI ☒ NON BEI


MATERIAL UNTUK REPAIR :

PART NAME	PART NO	QTY
Terminal	7116-2874	36 Pcs
Terminal	1060-16-0122	6 pcs
Rubber seal	7157-2571-80	36 Pcs
Connector	7123-6214-40	36 Pcs
Connector	DT04-2P-E005	3 Pcs
Retainer	W2P	3 Pcs

1. Modif harness PC135F pada posisi AC03 dari connector DT ke connector 7123-6214-40 sebanyak 36 pcs

Before :


After :




2. Modif connector untuk Oil Cooler PC210 HARVESTER sebanyak 3 pcs

Before :


After :



3. Assy No



4. Type Unit



CONFIRM "OK"

Disetujui	Diperiksa	Dibuat
Asst Manager QA	Leader QA	Repairman